

**NEWPORT MESA UNIFIED SCHOOL DISTRICT
CHANGE ORDER REQUEST**

EXPLANATIONS CONTINUED:

Change CMHS: COR #03 - Cancellation fee for BC Controller Enclosures (3) by Alliance Air Products

Scope: Cancellation charge for submittal data and engineering.

Reason: Fabrication lead time was going to exceed scheduled installation.

Origin: Unforeseen Field Condition

Funding Category: Field

Change CMHS: COR #06 - Cancellation credit for BC Controller Enclosures (3) by Trane

Scope: Credit from Trane for CMHS for switching BC Controller enclosures.

Reason: Equipment procurement was bid separate from installation to meet project schedule. Due to DSA changes, the Trane BC controllers would not meet the project specification and a new manufacture was required.

Origin: DSA

Funding Category: Field

**NEWPORT MESA UNIFIED SCHOOL DISTRICT
CHANGE ORDER REQUEST**

EXPLANATIONS CONTINUED:

Change NHHS: COR #01 - Mitsubishi/Trane condensing unit efficiency change

Scope: Specification change of equipment.

Reason: Working with the manufacture, it was determined that the specification could be met with less expensive equipment. This also helped decrease equipment lead times.

Origin: Architect

Funding Category: Building

Change NHHS: COR #02 - Addendum #2 change to model and efficiency change by Design Engineer

Scope: Revisions of specification and quantity of equipment.

Reason: During DSA review, structural requirements changed resulting in a change of equipment specification and quantity.

Origin: DSA

Funding Category: Building

Change NHHS: COR #03 - Cancellation fee for BC Controller Enclosures (2) by Alliance Air Products

Scope: Cancellation charge for submittal data and engineering

Reason: Fabrication lead time was going to exceed scheduled installation

Origin: Unforeseen Field Condition

Funding Category: Field

Change NHHS: COR #04 - Cancellation credit for BC Controller Enclosures (2) by Trane

Scope: Credit from Trane for NHHS for switching BC Controller enclosures.

Reason: Equipment procurement was bid separate from installation to meet project schedule. Due to DSA changes, the Trane BC controllers would not meet the project specification and a new manufacture was required.

Origin: DSA

Funding Category: Field

Change NHHS: COR #07 - Greenheck OSA Supply fan model change due to performance change

Scope: Greenheck OSA supply fan model change due to performance change.

Reason: This change order reflects the changes in the exhaust fans per DSA addendum 3. This included an additional fans and modified fan specifications.

Origin: Architect

Funding Category: Building

Change NHHS: COR #08 - Greenheck OSA Supply fan expediting charge due to factory lead time

Scope: Expedite the exhaust fans requested in addendum 3.

Reason: The standard lead time for the exhaust fans requested in addendum 3 is 8 weeks. This change is to expedite the lead time to 4 weeks to meet the project schedule.

Origin: Architect

Funding Category: Building